


Massachusetts Water Resources Authority

Recent Storm Impacts on MWRA's Wastewater System

July 23, 2021

19-Day Rainfall




Chelsea Creek: 11.59" Columbus Park: 11.39" Ward Street: 12.15"

- MWRA's service area experienced over 11-inches of rainfall over an 18-day period
- Typical annual rainfall for Boston area: 43 inches distributed throughout the year



Deer Island Treatment Facility Flows

Deer Island Treatment Facility Flows and Rainfall June 28-July 18, 2021



South System Flows and Rainfall June 28-July 18, 2021



CSO Facility Activations

Storm Event	CSO Facility	Duration	Discharge Vol (MG)
July 1 st – 2 nd Rainfall 3.46"	Somerville Marginal CSO	11 hrs 30 min	21.18 MG
	Prison Point CSO	8 hrs 40 min	58.45 MG
	Cottage Farm CSO	11 hrs 30 min	21.18 MG
July 3 rd – 4 th Rainfall 2.21"	Somerville Marginal CSO	6 hrs 24 min	9.79 MG
	Prison Point CSO	6 hrs 10 min	26.38 MG
July 9 th – 10 th	Somerville Marginal CSO	7 hrs 10 min	24.81 MG
Rainfall 2.89"	Prison Point CSO	7 hrs 48 min	57.52 MG
	Cottage Farm CSO	5 hrs 29 min	21.16 MG
July 12 th	Somerville Marginal CSO	2 hrs 10 min	6.02 MG
Rainfall 1.53"	Prison Point CSO	3 hrs 30 min	15.98 MG
July 18 th Rainfall 0.56" Somerville Marginal CSO		4 hrs 19 min	1.37 MG



CSO Facilities Typical Year Performance Comparison

CSO Facility	Typical Year Performance*	June 30 th – July 18 th
Somerville Marginal CSO	30 activations, 100.53 MG	5 activations, 63.4 MG
Prison Point CSO	17 activations, 253.69 MG	4 activations, 158.33 MG
Cottage Farm CSO	2 activations, 8.95 MG	2 activations, 42.34 MG

* Top Ten Storms in Typical Year


Dura-		Avg	Max	Inter-	
tion	Volume	Inten	Inten	event	
hours	inches	in/hr	in/hr	hours	
23	2.76	0.12	0.65	12	
50	3.89	0.08	0.2	139	
18	1.34	0.07	0.44	91	
4	1.18	0.29	1.08	33	
72	2.91	0.04	0.66	29	
84	2.39	0.03	0.31	59	
7	1.14	0.16	0.63	12	
11	0.87	0.08	0.75	162	
13	1.19	0.09	0.51	127	
18	1.34	0.07	0.44	91	

Max Hourly Rainfall during July $1^{st} - 2^{nd}$ Storm 1.23 inches per hour = 5-10 year storm



SSO Discharges during July 9th Storm Event

- SSO Discharged: 9.79 MG (6.4 MG at Archdale)
- Notifications: DEP/EPA, Local Boards of Health, MWRA's website






- Staff burnout
 - Long hours
 - Back-to-back coverage
 - Vacation season
 - Mandatory standby

Water System Reservoirs

- Reservoir releases as rivers recede to maintain freeboard
 - Metropolitan back up reservoirs
 - Sudbury system
 - Wachusett reservoir
- Seasonal Quabbin transfer for water quality able to be maintained throughout
- Quabbin Reservoir spilling as of Tuesday July 20







Massachusetts Water Resources Authority

7155 Section 22 Rehabilitation Alternatives Analysis and Environmental Permitting



Phased Approach

- Test pits completed first to determine plan for borings
- 29 Phase 1 borings completed
- Phase 2 test pits and borings were not required


Cost Savings

 Overall, \$550,000 of the \$1.7 million condition assessment cost was saved



Section 22 Through DCR's Neponset River Estuary (ACEC), Boston







Section 22 Concrete Encasement


Test pits determined good condition of wood piles in marsh







Neponset River Crossing Internal Leak Detection Equipment



- Internal leak detection of 600-foot Neponset River Crossing found pipe in good condition
- Re-evaluate in 20 years



Section 21, Milton and Quincy


- Section 21 Pipe wall thickness good, but heavily tuberculated
- Rehabilitation is to clean and line





Recommended Construction Alternative

 Program reduced construction cost from \$50 million for full pipe replacement to \$26 million recommended plan





Massachusetts Water Resources Authority

Carroll Water Treatment Plant SCADA System Improvements Contract 7582

July 21, 2021



Carroll SCADA System Improvements



Typical Replacement PLCs

- Replace Legacy PLCs and Instrumentation panels (32 PLCs, 16 panels, 30 PC terminals)
- Install Redundant Fiber Optic Communication Network Loop Throughout Plant
- Install Hardened Redundant Industrial Servers
- New Server room (HVAC and Fire Suppression)
- Upgrade Cyber security and UPS power
- Operator Control Room Refurbishment
- Complex Cutover 24/7 Operation



Control Panel Replacement



An Existing panel and UPS






Operator Control Room Refurbishment

Existing Control Room



New Control Room



Bidders	Cost	
LeVangie Electric Co., Inc.	\$12,905,070	
Engineers Estimate	\$13,971,833	
Mass Electric Construction Co.	\$15,779,000	
J.F. White Contracting Co.	\$18,430,855	

- For approval
- Presenter:
 - Andrea Murphy, Director of Human Resources



Appointment of Program Manager, Tunnel

- For approval
- Presenter:
 - Andrea Murphy, Director of Human Resources



Appointment of Community Relations Coordinator, Tunnel

- For approval
- Presenter:
 - Andrea Murphy, Director of Human Resources



Appointment of Director, TRAC

- For approval
- Presenter:
 - Andrea Murphy, Director of Human Resources



Appointment of Program Manager, Wastewater

- For approval
- Presenter:
 - Andrea Murphy, Director of Human Resources

Delegated Authority Report - June 2021

- For information
- Presenter:
 - Michele Gillen, Director of Administration
 - Douglas Rice, Director of Procurement



Massachusetts Water Resources Authority


Memorandum of Understanding with Mass. Department of Fish and Game for Public Access Fishing Pier at Deer Island, Amendment 3



Deer Island Fishing Pier and Parking Lot









Deer Island Fishing Pier Parking Lot





Fishing Pier Parking Lot Opening Ceremony - June 24



- Contract Award
- Presenter:
 - Paula Weadick, Director of MIS